

YMDDIRIEDOLAETH HARBWR CAERNARFON
CAERNARFON HARBOUR TRUST

Rhybudd Morwriaeth Lleol
Local Notice to Mariners

Rhif – Number - 21/2020

06/09/2020

Y Fenai – Siart 1464 – Menai Strait – Chart 1464

Cynghorir morwyr bod perygl sylweddol i fordwo yn bodoli yn yr ardal a nodir isod ac mae'n bosibl y bydd yr ardal ehangach yn y Gogledd-ddwyrain a'r De-orllewin o ystyried y llinell angor yn methu ar unrhyw adeg. Credir bod y llong danddwr yn dal i fod yn ei lle

53°13.113' N 004°10.660' W

Cynghorir morwyr i lywio'n ofalus iawn ar hyd Terfynau'r Harbwr nes y gellir sefydlu lleoliad a diogelwch y llong

Mariners are advised that a significant danger to navigation exists in the area noted below and possible the wider area both Northeast and Southwest given the anchor line may fail at any time. The submerged vessel is believed to still be in position

53°13.113' N 004°10.660' W

Mariners are advised to navigate with extreme caution throughout the Harbour Limits until the vessels location and security can be established.

HARBOUR OFFICE, MANTON ST HELENS RD, CAERNARFON, GWYNEDD. LL55 2PF

01286 875355 hm@caernarfonharbour.org.uk www.caernarfonharbour.org.uk

David John O'Neill
Harbwr Feistr Caernarfon Harbour Master
Issue 3 controlled document will be available on YHCHT website.