



YMDDIRIEDOLAETH HARBWR CAERNARFON HARBOUR TRUST



HARBOUR MASTERS REPORT 8th February 2023

Part 1

NEW OFFICE LOCATION.

We have now fully relocated the Harbour Office function to Ty Seiont, St Helens Rd.

Harbour office

Porthi Dre

Ty Seiont

St Helens Rd

Caernarfon

LL55 2YD

Telephone and email addresses remain the same.

NAVIGATION

NOTICE TO MARINERS

None to date

AIDS TO NAVIGATION

Channel Surveying will be undertaken in the coming weeks, in preparation for ensuring we offer the most appropriate positions for our AtoNs.

AtoN	Date	Action undertaken	Condition	Next Inspection
SWM	13/10/22	Recover	5%	03/23(deploy)
C1	13/10/22	Lift, Clean, Inspect	15%	09/23
C2	13/10/22	Lift, Clean, Inspect	5%	09/23
C3	13/10/22	Lift, Clean, Inspect	10%	09/23
C4	13/10/22	Lift, Clean, Inspect	5%	09/23
C5	13/10/22	Lift, Clean, Inspect	30%	03/23
C6	13/10/22	Lift, Clean, Inspect	25%	09/23
Mussel Bank	15/06/22	Lift, Clean, Inspect	30%	03/23
C7	14/11/22	Lift, Clean, Inspect	15%	03/23
TEMP	14/11/22	Lift, Clean, Inspect	10	09/23
C8	14/11/22	Lift, Clean, Inspect	10%	09/23 (Paint)
C9 C'fon	14/11/22	Lift, Clean, Inspect	35%	03/23
Change Buoy	14/11/22	Lift, Clean, Inspect	45%	03/23 (change out)
C10	14/11/22	Lift, Clean, Inspect	New	03/24
C11	11/10/22	New	0%	09/23
C12	Outstanding	Lift, Clean, Inspect	35%	03/23
C13	14/10/22	Lift, Clean, Inspect	40%	03/23 (change Out)
Traeth Gwyllt	14/1022	Lift, Clean, Inspect, New Chain and Shackles	0%	09/23
Temp	14/11/22	Lift, Clean, Inspect	10%	03/23
C14	14/10/22	Lift, Clean, Inspect	15% (sanded)	03/23
C9 Felin	Outstanding			
Bi furification Buoy	Outstanding			

Along with the outstanding C9(felin) and Biofortification buoy the 5knt speed limit markers still need inspected.



YMDDIRIEDOLAETH HARBWR CAERNARFON HARBOUR TRUST



HARBOUR MASTERS REPORT 8th February 2023

Part 1

Trinity house inspection with the remaining items requiring attention.

Place	AtoN No	Aid To Navigation	Aid Type	Defect	Action
P0312	N02814	Submarine Cable Crossing East Bank	Unlighted Beacon	Requires Painting	Anticipated 03/2023.
P0312	N02815	Submarine Cable Crossing West Bank	Unlighted Beacon	Requires Painting	Anticipated 03/2023.
P0312	N12536	Swelly Rock	Lighted Beacon	Requires Painting	Anticipated 03/2023.

Paint and painting equipment has been purchased to repaint the Llanddwyn Small Light Tower. This will be undertaken as weather allows but will be undertaken in line with the intended action date above of 03/23.

I am currently making arrangement with Trinity House for the annual inspection of our AtoNs. , anticipate late Feb to early March. As is standard practice, I will report the finding in the subsequent HM report.

PILOTAGE

No Acts to date.

There is a possibility of two cargos of slate for export on the 6th of Feb and the

MOORINGS

The moorings in the river Seiont will be inspected and maintained in February.

There are a number of old ground chains in the river Seiont that I intend to recover.

Clearance work upstream in the river Seiont has begun. A number of shopping trollies and trees have and will be removed.

Work to arrange the annual service of the moorings in y Felinheli has begun. The first suitable set of neap are 27/2/23 through until the 2/3/23 but unfortunately the divers are not available.

The task is now provisionally booked for 14,15,16 and 17/3/23.

SEIONT IV

The vessel is afloat and ready for service. A new generator/Welder has been purchased to replace a defuncted equipment.

Y FORYD

The vessel is afloat and ready for service.