



YMDDIRIEDOLAETH HARBWR CAERNARFON HARBOUR TRUST



HARBOUR MASTERS REPORT 3rd May 2023

Part 1

PMSC

On the 21/3/2023 I am pleased to report that The MCA undertook a Port Marine Safety Code Health Check. We are still awaiting the report.

MARINE ADVISORY COMMITTEE

Further to my last, we are now anticipating a May MAC, further work is required in bringing the members back together.


NAVIGATION

NOTICE TO MARINERS

- 01/23 C1 New position
- 02/23 C2 New position
- 03/23 C3 New Position
- 04/23 C8 New Position
- 05/23 SWM back on station in new position
- 06/23 Grampian castle seasonal buoy on station.

AIDS TO NAVIGATION

Current Channel approaches to Caernarfon Chart.





YMDDIRIEDOLAETH HARBWR CAERNARFON HARBOUR TRUST



HARBOUR MASTERS REPORT 3rd May 2023

Part 1

CAERNARFON HARBOUR TRUST FLOATING AtoN POSITIONS Dated 20/04/2023 as submitted to Trinity House for quarterly Consent.

LLANDDWYN ISLAND SW ROCK BUOY S CARDINAL	N02791	53° 07'.79 N	004°25'.05 W	Unlit
LLANDDWYN ISLAND E ROCK BUOY S CARDINAL	N2792	53° 08'.04 N	004°24'.47 W	Unlit
SAFE WATER MARK	N17963	53° 06'.95 N	004°25'.11 W	L Fl.10s
C 1 STARBOARD	N02793	53° 07'.06 N	004°24'.67 W	Fl.G.5s
C 2 PORT	N02794	53° 07'.14 N	004°24'.38 W	Fl.R.10s
C 3 STARBOARD	N02795	53° 07'.19 N	004° 23'.84 W	Q.G
C 4 PORT	N02796	53° 07'.15 N	004°23'.03 W	Q.R
GRAMPIAN CASTLE		53° 07'.26 N	004° 22'.96 W	Fl(4) Y10s
C 5 STARBOARD	N02797	53° 07'.14 N	004°23'.37 W	Fl.G(2).5s
C 6 PORT	N02798	53° 07'.16 N	004°21'.91W	Fl.R.5s
MUSSEL BANK	N02799	53° 07'.22 N	004°20'.93 W	Fl.R(2).5s
C 8 PORT	N02801	53° 07'.62 N	004°19'.45 W	Fl.R.3s
C 10 PORT	N02802	53° 08'.02 N	004°18'.50 W	Q.R
C 7 STARBOARD	N02803	53° 08'.18 N	004°18'.13 W	Q.G
C 12 PORT	N02804	53° 08'.50 N	004°17'.38 W	Fl(2)R.10s
C 9 STARBOARD	N02805	53° 08'.55 N	004°16'.92 W	Fl.G.2s
CHANGE BUOY S CARDINAL	N02834	53° 08'.81 N	004°16'.74 W	VQ(6)+LFl 10s
SEIONT RIVER BIFURCATION	N14410	53° 08'.51 N	004°16'.75 W	Unlit
TRAETH GWYLLT STARBOARD	N10125	53° 09'.23 N	004°16'.12 W	Fl(2)G.10s
C 13 STARBOARD	N02811	53° 09'.54 N	004°15'.90 W	Fl(4)G.10s
C 11 STARBOARD	N02812	53° 09'.88 N	004°15'.63 W	Fl(2)G.5s
C 14 PORT	N02813	53° 10'.23 N	004°15'.41 W	Fl.R.5s
C 9 STARBOARD PORT DINORWIC	N08507	53° 10.65 N	004°13'.95 W	FL(3)G.10s



YMDDIRIEDOLAETH HARBWR CAERNARFON HARBOUR TRUST

HARBOUR MASTERS REPORT 3rd May 2023

Part 1





YMDDIRIEDOLAETH HARBWR CAERNARFON HARBOUR TRUST

HARBOUR MASTERS REPORT 3rd May 2023

Part 1





HARBOUR MASTERS REPORT 3rd May 2023 Part 1

PILOTAGE

The Deo gloria delivered to cargos of sand to port Penrhyn on the 17/4/23 and the 18/4/23

MOORINGS

A 12.49m sailing vessel moored on a Private mooring in Rowen bay parted its warps at some point during the evening of the 11th April in unfavourable weather. The vessel was reported to be ashore on Church island. An unsuccessful attempt to re-float her was undertaken on the local HW on the 12th April, unfortunately the vessel had neaped herself. The tides were insufficient until the Sunday 16th April when she was successfully floated and towed to port Penrhyn to be hauled out.



SEIONT IV

The vessel is afloat and ready for service. The usual annual painting has also commenced.

Y FORYD

The vessel is afloat and ready for service.